



CADW Scheduled Ancient Monument site visit report.

VISITED BY

F.Grant

FILE

GENERAL

SITE NAME

Deeside Slateworks

SITE No.

DE246

VISIT DATE

08/09/2016

REASON

SMC

CONDITION TREND

CONDITION CURRENT

VULNERABILITY

OVERALL RISK LEVEL

NOTES

The visit was made in response to a call from [] to inform me that the track resurfacing works as per SMC application were to begin. I met with [] on site at approximately 13:30. The dirt track crosses the tramline from the public road in the east, then snakes north-westwards across the pasture. Locally sourced crushed slate chips have been laid over the crossing point of the tramline to form a surfaced track c.2.5-3m max width. Surfacing has not continued right up to the junction of the track and the public road, as [] explained that this area was under dispute with their neighbour. This particular area appears to fall outside the scheduled area anyway.

All works appear to have been carried out in accordance with the SMC. Additional verbal advice was given at the time of the visit as regards managing vegetation growing on the tramline revetment walls.